

The Finest Machine Tools

IL - (630) 321-1500

WI - (262) 789-1600



Did You Know? Tool Load Monitoring: Do's and Don'ts

Tool Load Monitoring is a helpful tool that can stop a machine before catastrophic tool failures, avoid lost time, and allow for safer lights out manufacturing. It does this by:

- Stopping a dull drill before it breaks and the tool melts down
- Stopping subsequent tools from being broken in a "chain reaction" of broken tools
- Detecting a roughing insert that needs changing, and that may cause a finishing tool to break or go oversized

Tool Load Monitoring is the kind of option that pays for itself in the long run; but not everyone is familiar with some of the major do's and don'ts...

What is Tool Load Monitoring? Read More Here...

Tool Load Monitoring Do's:

- Do use for tools that are roughing, drilling, or taking heavy loads
- Do use it to help protect yourself when running "lights out" by shutting down a machine before or when a breakage occurs
- Do use it to detect spindle loads and axis loads
- Do use it on the appropriate axis that is performing the cutting and is detectable

Tool Load Monitoring Don'ts:

- Don't use it for extremely light loads, the Load Monitor may set a zero in the Base load value. Turn the axis off if it does
- Don't use it on a spindle in G96 mode, G96 causes high loads on the spindle as it accelerates and slows
- Don't use it for heavy interrupted cuts, steady loads are best
- Don't approach a part using a fast feed-rate, this can throw off detecting accuracy
- Don't use it for axes that are not moving or not being used

Tricky Workpiece? Let our Expert Engineers Take a Look...

Example of Monitoring on Mitsubishi Control

Tool number by state											Peak	value	Tool	Numbe	r		
	1	2	3	4	5	6	7	8	9	10	#	01					
	11	12	13	14	15	16	17	18	19	20	Peak	value					
	21	22	23	24	25	26	27	28	29	30	X1	0	X2	0	X3		0
	31	32	33	34	35	36	37	38	39	40	71	0	72	0	73		0
	41	42	43	44	45	46	47	48	49	50	V1	0	V2	0	20		
	51	52	53	54	55	56	57	58	59	60		0	۲Z	U	~~		0
	61	62	63	64	65	66	67	68	69	70		U			62		0
	71	72	73	74	75	76	77	78	79	80							
	81	82	83	84	85	86	87	88	89	90	S1	0					
	91	92	93	94	95	96	97	98	99		S2	0					
											\$3	0					
Normal Level										S4	0						
Warning Level											1						
Cycle stop Level																	
Alarm stop Level																	
Than stop Lever																	
ľ	MEM	1 RD	Y 2F	RDY	3 RDY	01										OVR	100%
				S	et s	W MC		a Me	SSage		De		Calc				
TMSamp TMSet TMStatusAL#Srch												I/	0		Men	u SEL	

Miss our Last Tech Tips? Click Below!

